## ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ,ਲੋ:ਨਿ:ਵਿ:ਭ ਤੇ ਮ ਸ਼ਾਖਾ,

ਦੂਜੀ ਮੰਜਿਲ ਬਲਾਕ-2,ਜਿਲ੍ਹਾ ਪ੍ਰਬੰਧਕੀ ਕੰਪਲੈਕਸ,ਸੰਗਰੂਰ। ਟੈਲੀਫੋਨ/ਫੈਕਸਨੰਬਰ. 01672-234114 EMAIL:-<u>sdeprovincialsangrur@gmail.com</u>

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ ਐਮ.ਐਲ.ਜੀ. ਕੋਨਵੈਂਟ ਸਕੂਲ, ਚੀਮਾਂ।

ਨੰਬਰ 1073

ਸਿਤੀ 21-12-2622

ਵਿਸ਼ਾ

ਸਮਾਂ 2023-27, ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ। ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 40000/– ਜੀ.ਆਰ ਨੰ: <u>66.531੫</u> ਮਿੜੀ <u>ਕੈ\-\2-22</u> ਰਾਂਹੀ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ। ਨੱਥੀ/ ਸਰਟੀਫਿਕੇਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

> ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

## **Building Safety Report**

Name of School:- MLG Convent School, Cheema.

I have visited the above mentioned college building along with Sh Gurpreet Singh Dhillon A.E and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building such as Architectural Drawings. Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications. Test Reports of Material used Quality Control reports and certificate from Engineer in Charge for construction are not available.
- b) In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) A separate certificate regarding Fire Fighting & Fire Safety Guidelines should be obtained from the competent authority.
- e) A separate certificate regard Electrical Works should be obtained from the competent autority.
- f) The owner of the building/ Management is fully responsible regarding safety of building from all angles in spite of this report.
- g) The covered area of the building is 33000 Sq.ft.
- h) This Report is not valid for legal purpose.

7

- i) This building visually seems safe to occupy for the normal use up to: 31-03-2027
- j) This Building Certificate should not be considered as NOC for Road Access which will be taken separately by the School as per Government Policy No. 5/13/2018-3BR3/1294287/3

Sub Divisional Engineer Provincial Sub Division PWD, B&R Sangrur.